# Strips Drip by sensative

Magnet

Mounting plate

Moisture pads

video tutorials

www.sensative.com/drip

Z-WAVE PLUS

1

ADD +

Put your gateway into add mode

2

Remove magnet (see 1 short LED blink)

3

1 long LED blink means success

4

15sec

Hold in hand and look for status change in your gateway

5

Remove the protective tape from Strips Drip adhesive

6

STRIPS SIDE

Mount Strips Drip on the marked "Strips side" of the mounting plate

7

Remove the protective tape from the mounting plate and place Strips Drip firmly on the surface

8

Place Strips Drip so that the moisture detection pads will soak any leaking water

SENSATIVE STRIPS DRIP ILLUSTRATIONS MANUAL

Colors used:
PANTONE 285C - Blue, background first spread
PANTONE 2718C - Light Blue, Box background for QR code
CMYK - All other details
Black

Coating on all surfaces: Matte UV Coating